

FIG.4









FIG.5











Hiroshi OKADA, et al. Q78713 HITACHI UNISIA AUTOMOTIVE, LTD. Alan J. Kasper 202-293-7060 January 5, 2004 9 of 9

